




Drawer installation to the cabinet.




Front panel adjustment.



Drawer disassembly.



Drawer removal



OÜ OSMARGO
Suur-Paala 13
13619 Tallinn
Estonia
tel.: +372 638 10 18
osmargo@osmargo.ee
www.osmargo.ee

